




Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
THE GROVE	O/S 2	Damaging	Extensive f/w uplift, f/w cracking	Prunus Kanzan	Plant in verge o/s 2, (same position as felled tree)	Malus 'Rudolph'
THE GROVE	O/S 26	Damaging	Kerbs displaced/pushed by roots directly behind	Prunus Kanzan	Plant in verge o/s 26, (same position as felled tree)	Malus 'Rudolph'
THE GROVE	O/S 60	Damaging	Growing entirely within c/w, impossible to retain/work round	Fraxinus excelsior	Plant in verge o/s 60, (adjacent to felled tree position)	Malus 'Rudolph'
THE GROVE	O/S 7	Damaging	F/W mounded, recently patched, cracking again	Prunus Kanzan	Plant in verge o/s 7 (same position as felled tree)	Malus 'Rudolph'
THE GROVE	O/S 3	Damaging	F/W mounded, recently patched, cracking again	Prunus Kanzan	Plant in verge o/s 3 (same position as felled tree)	Malus 'Rudolph'
THE GROVE	O/S 1	Damaging	F/W mounded, recently patched, cracking again	Prunus Kanzan	Plant in verge o/s 1 (same position as felled tree)	Malus 'Rudolph'